

TABLE OF CONTENTS

	<u>Page</u>
	<u>Page</u>
1.0 Project Overview	1
1.1 Purpose.....	1
1.2 Project Summary.....	3
1.3 Contact Information.....	1
1.4 Directions to the Site.....	3
2.0 Mitigation Requirements and Performance Standards	4
2.1 Mitigation Requirements	4
2.2 Mitigation Performance Standards	4
2.3 Monitoring and Reporting Requirements	6
3.0 Mitigation Performance	8
3.1 Conservation Easement.....	8
3.2 As-built Evaluation	8
3.3 Wetlands	8
3.3.1 Wetland Mitigation Areas.....	8
3.3.2 Wetland Acreage.....	9
3.3.3 Vegetative Composition and Cover	10
3.3.4 Woody Plant Survival.....	11
3.4 Streams.....	11
3.4.1 Stream Restoration/Improvement Areas	12
3.4.2 Qualitative Habitat Evaluation Index.....	12
3.4.3 Riparian Woody Plant Survival	13
4.0 Compliance with Performance Standards	14
5.0 Corrective Actions	15
5.1 Wetlands	15
5.2 Streams.....	15
5.2.1 Piney Creek North.....	15
5.2.2 Piney Creek South.....	16
5.2.3 Long Run	16
6.0 Conclusions and Recommendations	17
6.1 Wetland Mitigation Areas.....	17
6.2 Stream Improvement/Restoration Areas	17
7.0 References	19

TABLES

- Table 1 – Wetland Plant Community Evaluation
- Table 2 – Woody Plant Inventory and Survival Rates
- Table 3 – Stream Restoration Measures

FIGURES